## **BUNN**®

## **CWTF APS Brewing Instructions**







1. Insert a BUNN<sup>®</sup> filter into the 2. Pour in fresh coffee. funnel.

3. Shake funnel gently to level grounds.





of the brewer.

funnel.

4. Slide funnel into the funnel rails 5. Place an empty airpot under the 6. Place "ON/OFF" switch in lighted upper position.



7. Momentarily press and release the "START" switch.



8. When brewing is complete, discard the grounds and filter.



## CWTF APS Brewer and Airpot Cleaning Instructions







2. Clean mineral deposits and 3. rinse. Make sure all holes are open.



3. With the sprayhead removed, insert the deliming spring all the way into the sprayhead tube. Move back and forth five or six times. Replace sprayhead.



4. Use a clean damp cloth rinsed 5. in mild, non-abrasive detergent to clean all surfaces.



5. Open the airpot by pressing the 6. buttons located on either side of the nozzle and lifting.



Remove the pump tube assembly.



7. Thoroughly rinse the entire server.



8. Use a clean damp cloth rinsed in mild, non-abrasive detergent to clean all surfaces.